Boysen-Perry House NE corner N. Palafax and E. Wright Sts. Pensacola Escambia County Florida HABS NO. FLA-149
HABS
FLA.

17-PENSA
8-

PHOTOGRAPHS
WRITTEN HISTORICAL AND DESCRIPTIVE DATA

ADDENIA:

Historic American Buildings Survey
National Park Service
Eastern Office, Design and Construction
143 South Third Street
Philadelphia 6, Pennsylvania

HISTORIC AMERICAN BUILDINGS SURVEY

HABS No. FLA-149

BOYSEN PERRY HOUSE

HABS FLA

Location:

NE cornsr N. Palafax and E. Wright Streets,

Psnsacola, Escambia County, Florida

17-PENSA 8-

Present Owner:

Scottish Rite Building Association

Present Occupant:

Scottish Rite Building Association

Present Use:

Lodge

Brisf Statsment of Significance:

This structure, built about 1867, served as a Consulats of Sweden and Norway, and later as a home of Edward Aylesworth Psrry, Governor of

Florida 1885-1889.

PART I. HISTORICAL INFORMATION

A. Physical History:

l. Original and subsequent owners: 1867, Charles F. Boyssn 1882, Edward Aylesworth Psrry 1900, J. A. Chaffin 1922, Scottish Rite Bldg.

Association

- 2. Dats of ersction: c. 1867
- 3. Original plans, construction: Boysen acquired materials from wrecked buildings and used them in this structurs.
- 4. Notes on alterations and additions: Building sxtsnsively remodeled 1922. Back porch enclosed; cupola and four chimneys with pots removed. Modern appendages.
- 5. Important old views: Photograph in possession of Scottish Rite Lodgs, undated, shows cupola, four chimneys, and dormers.
- 6. Sources of Information:
 - a. Howard Mc Lean, secretary, Scottish Rite Building Association, P.O. Box 901, Psnsacola.
 - b. Fsderal Writsrs' Project, Florida, A Guide to the Southernmost State (Nsw York: Oxford University Press, 1939), pp. 241-242.

BOYSEN-PERRY HOUSE HABS No. FLA-149 (Page 2)

PART II. ARCHITECTURAL INFORMATION

A. General Statement:

- Architectural character: this is a two-and-a-half story, stuccoed brick structure with porches on the front and sides of the first and second floors.
- 2. Condition of fabric: Exterior good, slightly modified from original. Interior extensively remodeled. Large modern addition not included in survey.

B. Technical Description of Exterior:

- 1. Over-all dimensions: Approx. 71' (facing south) x 62' (including porches but not including modern appendage).
- 2. Foundations: Brick foundation wall under house. Brick piers under porch columns connected with brick wall.
- 3. Wall construction: Brick wall covered with stucco, scored rustications 17" x 49". Walls carried above the porch roofs in a parapet.
- 4. Porches: Forches: first and second floor, front and two sides; built-up wood columns, 10" x 10" first floor, 8" x 8" second floor, square and paneled each side; Balustrade at second floor, molded rail.
- 5. Chimneys: None

6. Openings:

- panel door (top two arched), transom of one light, side lights of two lights each, wood cornice. Doorway to second floor of porch directly above entrance doorway is similar.
- b. Windows: Heavy wood frames, dentil course in cornices, extend to floor with 6 over 6' and 6 over 9' sash. House originally had shutters, indicated by shutter hardware.

7. Roof:

a. Shape and covering: Hip roof over porches to parapet wall, composition roofing.

- b. Cornice and eaves: Boxed eave, simple wood cornice on porches
- c. Dormers: Gable roof, dormers on porch roofs, composition roofing, two double-hung windows per dormer. House originally had cupola.
- C. Technical Description of Interior:
 - 1. Floor plans:
 - a. First floor: Central hall flanked by four rooms. First floor left rooms connected by sliding doors. Original back porch closed.
 - b. Second floor: Extensively remodeled to form single space (lodge room).
 - c. Attic: inaccessible
 - 2. Stairways: Original stairway removed. Second floor accessible by stair in modern appendage.
 - 3. Flooring: 4½" vertical grain pine, modern wood strips, plastic tile.
 - 4. Wall and ceiling finish: paper over plaster, acoustical tile, plaster, wood strip ceiling; wall of right rear room painted scored stucco.
 - 5. Doorways and doors: Four panel wood doors. Double doorway between connected parlors with two six-panel sliding doors.
 - 6. Trim: Slate fireplaces and mantels (painted).
 - 7. Hardware: Shutter hardware and some keyhole covers remain.
 - 8. Heating; Modern steam heat. Original fireplaces in each room, all closed.
- D. Site: Faces south NE corner at N. Palafax and E. Wright Streets, some large trees, no landscaping.

Frepared by F. Blair Reeves College of Architecture and Fine Arts University of Florida Gainesville, Florida February 1962 Addendum to Boysen-Perry House (Scottish Rite Temple)
Northeast corner of N. Palafax and E. Wright Streets Pensacola Escambia County Florida

as recorded in 1962

HABS, FLA, M-PENSA,

HABS No. FL-149

PHOTOGRAPHS

Historic American Buildings Survey Heritage Conservation and Recreation Service Department of the Interior Washington, D.C. 20243